



ALL TRUSSES:  
 IMPORTANCE FACTOR I = 1.0 (CAT II)  
 THERMAL FACTOR Ct = 1.2  
 EXPOSURE Ce = 1.0  
 PARTIALLY ENCLOSED  
 40 PSF COMBINED LOADING

4 SCALE

DESIGNED	#	DATE
DRAWN	#	
CHECKED		
APPROVED		

MATT NEENAN  
 DRAWING FOR TRUSS  
 MANUFACTURER  
 SUSQUEHANNA COUNTY, PA

United States  
 Department of  
 Agriculture  
**USDA**  
 Natural Resources  
 Conservation Service

FILE NO.
DRAWING NO.
SHEET 24 OF 27